Woodpark Lane Pond Repair Project

Stormwater Management Division

Bureau of Environmental Services

9801 Broken Land Parkway, Columbia, MD 21046


Community Outreach Meeting Date: 09/20/2023



Agenda

- Background and Overview
- Current Conditions
- Proposed Design
- Questions / Comments

Background and Overview



Existing Conditions









Existing Conditions










Project Need?

Public Safety Concerns

- Existing principal spillway: riser and barrel pipe show signs of corrosion, barrel pipe clogging with silt and debris.
 - Needs to be replaced
- Woody vegetation overgrown on and adjacent to the embankment do not meet the safety requirement.
 - Needs to be remove
- All existing inlet points need to be replaced with inflow protection
 - Enhance the water quality, plunge pools.
- Forebays will be added to improve water quality treatment.
 - Needs to be added

Proposed Design





Example
Proposed
ConditionsPhotos









Project Goals

 Repair the pond and bring it up to the current standards

Minimize the duration of construction

Minimize Limit of Disturbance (LOD)

Construction

Construction is anticipated to start Fall 2023

Duration

Approximately 4-5 months (Weather Permitting)

Construction Hours

 Monday to Friday, 7AM to 5PM. Contractor may mobilize sooner than 7:00 AM but will not be permitted to start construction before 7:00 AM.

Safety

 Construction site will be fenced with orange construction safety fence

Access

- Access road is proposed from the existing BG&E maintenance access Rd from Murray Hill Rd.
- The trail which is adjacent to the pond will be closed 1-3 days for a pipe installation.

What to expect during Construction







Next Steps

Final Construction Documents

Permits

Pre-construction signs

Notification Letters 30 days prior to starting construction

Questions?

- Mark Richmond, Howard County DPW, Bureau of Environmental Services, Stormwater Management Division (410-313-6413, <u>msrichmond@howardcountymd.gov</u>)
- Bill Liu, Howard County DPW, Bureau of Environmental Services, Stormwater Management Division (410-313-6416, bliu@howardcountymd.gov)
- Yinting Hou, KCI Technologies, Inc (<u>Yinting.Hou@kci.com</u>)

A copy of the presentation can be found at:

https://www.howardcountymd.gov/public-works/communityinvolvement